

## EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	2	"20070271771"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 12:43
L2	2	"5396696".pn.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 12:43
L3	1	"4743331".pn.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 12:43
L4	2	"6737603".pn.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 12:44
L5	9	("3234354"   "3435184"   "4697058"   "4950866"   "5115111"   "6100511"   "6369346").PN.	US-PGPUB; USPAT; USOCR	OR	OFF	2008/08/16 12:44
L6	0	welding same head with brush with "DC motor"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 12:52
L7	0	welding same head same brush with "DC motor"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 12:52

L8	0	electronic same inductor same brush with "DC motor"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 12:52
L9	21	weld\$3 same brush with "DC motor"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 12:53
L10	5	electric same weld\$3 same brush with "DC motor"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 12:53
L11	0	inductor same weld\$3 same brush with "DC motor"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 12:55
L12	57	inductor same coil same welder weld\$3 same brush with "DC motor"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 12:56
L13	0	inductor same coil same welder same brush with "DC motor"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 12:56
L14	1180	spot same electric with weld	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 12:58
L15	1	inductor same spot same electric with weld	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 12:58

L16	84	inductor same electric with weld	US-PGRUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 12:58
L17	0	inductor same electric with weld with "DC motor"	US-PGRUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 12:59
L18	54024	DC adj motor	US-PGRUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 12:59
L19	1	16 and 18	US-PGRUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 12:59
L20	44	enameled same wires with weld\$3	US-PGRUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 13:01
L21	0	18 and 20	US-PGRUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 13:01
L22	0	18 and 20 and motor	US-PGRUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 13:02
L23	9	("3234354"   "3435184"   "4697058"   "4950866"   "5115111"   "6100511"   "6369346").PN.	US-PGRUB; USPAT; USOCR	OR	OFF	2008/08/16 13:04
L24	19	("4950866").URPN.	USPAT	OR	OFF	2008/08/16 13:06
L25	6	("5152450").URPN.	USPAT	OR	OFF	2008/08/16 13:07

L26	10	("3789183"   "4387283"   "4572772"   "4575602"   "4580713"   "4594493"   "4611747"   "4674671"   "4705204"   "4950866").PN.	US-PGPUB; USPAT; USOCR	OR	OFF	2008/08/16 13:08
L27	0	SMD with enameled same wires with welder	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 13:13
L28	44	enameled same wires with weld\$3	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 13:14
L29	2	enameled same wires with weld\$3 and brush \$3	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 13:14
L30	0	wires same camera same microscope same spot with weld\$3	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 13:16
L31	12	wires same microscope same spot with weld\$3	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 13:17
L32	0	microscope same spot with weld\$3 with DC same motor	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 13:18
L33	12	spot with weld\$3 with DC same motor	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 13:18

L34	5	microscope same wires with spot with weld\$3	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 13:20
L35	3	("4500031").URPN.	USPAT	OR	OFF	2008/08/16 13:21
L36	3	("3512248"   "3775579").PN.	US-PGPUB; USPAT; USOCR	OR	OFF	2008/08/16 13:21
L37	12	microscope same spot with welder	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 13:22
L38	2	microscope same spot with welder and motor	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 13:23
L39	5	microscope with weld \$3 with motor	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 13:23
L40	33	microscope with weld \$3 same head	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 13:24
L41	39	("3383491").URPN.	USPAT	OR	OFF	2008/08/16 13:27
L42	3	("3828156").URPN.	USPAT	OR	OFF	2008/08/16 13:30
L43	47	microscope with weld \$3 same spot	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 13:34
L44	87434	weld\$3 same spot	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 13:36

L45	143	44 and 18 and brushless	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 13:37
L46	1	45 and microscope	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 13:37
L47	59351	microscope same weld \$3 samw motor with brush\$3	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 13:39
L48	3	microscope same weld \$3 same motor with brush\$3	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 13:39
L49	0	weld\$3 same head with connector same rotation same motor	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 13:47
L50	110	weld\$3 same head with connector same motor	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 13:47
L51	35	weld\$3 same head with connector with motor	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 13:48
L52	20	weld\$3 same head with connector with motor and rotation	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 13:48
L53	3	("3681560").URPN.	USPAT	OR	OFF	2008/08/16 13:51

L54	0	microscope same weld \$3 same head with rotation same motor	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 13:52
L55	7	microscope same weld \$3 same head with motor	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 13:52
L56	347	weld\$3 same head with rotation with motor	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 13:54
L57	1	microscope and weld \$3 same head with rotation with motor	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 13:54
L58	115145	Shitong Yang.inv.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 13:56
L59	0	58 and 9	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 13:57
L60	0	58 and 55	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 13:57
L61	4	58 and 28	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/16 13:57

8/16/2008 1:59:26 PM

C:\Documents and Settings\nguyen53\My Documents\EAST\Workspaces\11387929.wsp